

CAMBRIDGE HISTORICAL COMMISSION
831 Massachusetts Avenue, 2<sup>nd</sup> Fl., Cambridge, Massachusetts 02139
Telephone: 617 349 4683 TTY: 617 349 6112

E-mail: histcomm@cambridgema.gov URL: www.cambridgema.gov/Historic

	APPLICATION FOR CERTIFICATE			
1.	The undersigned hereby applies to the Cambridge Historical Commission for a Certificate of (check one box): Appropriateness, Nonapplicability, or Hardship, in accordance with Chapter 40C of the Massachusetts General Laws and/or Chapter 2.78 of the Municipal Code.			
2.	Address of property: 795 Massachusetts Avenue , Cambridge, Massachusetts			
3.	Describe the proposed alteration(s), construction or demolition in the space provided below: (An additional page can be attached, if necessary).			
	The Project consists of the following exterior facade improvements -  1. Installation of masonry repairs at exterior brownstone and granite masonry.  2. Removal and replacement of paint and glazing putting at wood windows and installation of epoxy and dutchman repairs at wood windows.  3. Gilding of balcony text and tower clock hands and numerals.  4. Removal and replacement of exterior flagpole on the south elevation.  5. Removal and replacement of roofing at balcony on the south elevation.  6. Removal and replacement of bird protection on the north elevation and tower.  7. Cleaning of exterior masonry at north elevation.  8. Installation of lightning protection at the flagpole and building.  9. Relocation of the existing balcony signage on the south elevation that overlaps the gilding.  10. Replacement of the existing tower light fixures for a more efficient fixutre with lighting controls.			
	ertify that the information contained herein is true and accurate to the best of my knowledge and lief. The undersigned also attests that he/she has read the statements printed on the reverse.			
Na	me of Property Owner of Record: Owen O'Riordan, Deputy City Manager, City of Cambridge			
Ma	ailing Address: 795 Massachusetts Avenue, Cambridge, MA 02139			
Te	Telephone/Fax: 617 349 4000 E-mail: ooriordan@cambridgema.gov			
Signature of Property Owner of Record:  (Required field; application will not be considered complete without property owner's signature)				
Na	me of proponent, if not record owner: Aoife Viglianti, Project Manager, DPW / City of Cambridge			
Ma	ailing Address: 147 Hampshire Street, Cambridge, MA 02139			
Те	lephone/Fax: 617 312 1287 E-mail: aviglianti@cambridgema.gov			
	r office use only): te Application Received: Case Number: 4905 Hearing Date: 222			

Date Issued:

Type of Certificate Issued:

# **Instructions for Completing this Application:**

An application must be filed with the Cambridge Historical Commission (CHC) before work begins. Twelve (12) copies of the application should be attached to twelve (12) copies of supplementary material such as sketches, scale drawings, site plans, specifications, or photographs sufficient to enable the CHC to understand the details of the work proposed and to make a determination on the application. Plans no larger than 11" x 17" are preferred. Please submit reduced copies of plans if originals are of a larger dimension. Do not use spiral bindings, plastic covers, or heavy stock (these will be removed prior to mailing). Double sided copies are encouraged to save paper and postage. See our website or call for a list of meeting dates and deadlines.

The CHC staff welcomes advance inquiries for interpretations or advice. Please call 617/349-4683. An application is considered incomplete without accompanying plans and drawings. The CHC reserves the right to determine an application incomplete at the time of hearing the application if it determines that the plans, drawings and other information submitted are not sufficient to enable it to determine whether to grant or deny a certificate.

Owners are urged to appear before the CHC in person or to designate an agent to act for them. The CHC will deem the agent to be authorized by the owner to make decisions regarding the extension or waiver of the period within which the CHC is otherwise required to make a determination on the application.

All meetings are open to the public.

# Administration of Historic Districts, Landmarks, and Protected Properties:

The administration of historic districts and landmarks is guided by the provisions of Ch. 40C of the Mass. General Laws and by Ch. 2.78 of the Code of the City Of Cambridge. Other properties may also be subject to CHC jurisdiction including properties with conditional variances and properties governed by individual preservation restrictions.

Any new construction, alteration of exterior architectural features, or demolition within an historic district or on the premises of a protected property or a designated landmark must be reviewed by the CHC. No building permit for such work on a protected property, designated landmark, or property within a historic district may be issued by the Inspectional Services Department until a certificate has been issued. The CHC must approve the alteration or construction of all structures, including signs, fences, walls, terraces, walks, driveways, light fixtures and the like, which are "open to view from a public street, public way, public park or public body of water," whether or not a building permit is required, and must approve changes in exterior color for properties within a historic district or as otherwise agreed.

Prior to each hearing, the CHC staff will take slides or digital photographs of the subject property in daylight with ordinary camera equipment for the purpose of documenting the publicly visible conditions of buildings and exterior architectural features for the CHC and the public to view at the hearing. More information can be provided on request.

The CHC issues three types of certificates. A <u>Certificate of Appropriateness</u> will be issued when the CHC has determined that the construction or alteration will be appropriate for or compatible with the preservation or protection of the historic district, designated landmark, or other protected property. A <u>Certificate of Nonapplicability</u> may be issued when an application does not involve an exterior feature, or when the exterior feature is not then subject to CHC review. <u>A Certificate of Hardship</u> may be issued when failure to approve an otherwise inappropriate project would involve substantial hardship to the applicant and the CHC determines that the project can be accomplished without substantial detriment to the purposes of the district, preservation restriction, or landmark designation.

The CHC considers each application on its own merits, and does not apply specific architectural guidelines. Landscaping with plant materials is not subject to CHC review unless it is planned in conjunction with alterations or new construction. The CHC must approve projects that are not incongruous with the historic aspects or the architectural characteristics of the protected property, landmark, or historic district.

**Print Form** 

# Cambridge - City Hall Facade Restoration

City of Cambridge 795 Massachusetts Ave. Cambridge, MA 02139

Sheet Number	Sheet Name				
1) General					
G000	Cover Sheet				
G001	Vicinity Map, Symbols + Abbreviations				
2.1) Architectura					
AD100	Demo Site Plan				
AD200	Demo Elevations				
AD201	Demo Elevations				
AD202	Demo Elevations				
AD203	Demo Elevations				
AD204	Demo Elevations				
AD500	Demo Details				
2.2) Architectura	1				
A100	Site Plan				
A101	Site Logistics Plan				
A200	Exterior Elevations				
A201	Exterior Elevations				
A202	Exterior Elevations				
A203	Exterior Elevations				
A204	Exterior Elevations				
A500	Window Details				
A501	Ornamental Metal & Gilding Details				
A502	Roofing & Flagpole Details				
A600	Existing Window Types				
3.1) Envelope					
EN001	General Notes				
EN200	South Elevation - Masonry Repairs				
EN201	East Elevation – Masonry Repairs				
EN202	North Elevation – Masonry Repairs				
EN203	West Elevation - Masonry Repairs				
EN204	Courtyard Elevations – Masonry Repairs				
EN300	Brownstone Masonry Repair Details				
EN300	Brownstone Masonry Repair Details				
EN301	Brownstone Masonry Repair Details				
3.2) Structural	Brownstone Masonry Repair Details				
S001	General Notes				
S002	Special Testing and Inspection Procedures South Elevation				
S100 S110	South Elevation Sections and Details				



Finegold Alexander Architects


77 North Washington St Boston, MA 02114 T 617.227 9272 F 617.227 5582


Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02-

House Doctor
Arup

CONSULTA

Project No.P0128.08 11/17/22 Construction Documents 50% PROGRESS SET





PROJECT TEAM:

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd. Waltham, MA 02451

Arup 60 State St, Boston, MA 02109



PROJECT INFORMATION

Cambridge - City Hall Facade 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08 ISSUE DATE: 11/17/22 PROJECT STATUS: Construction De DRAWN BY:


CHECKED BY

Vicinity Map, Symbols + Abbreviations

DRAWING HISTORY:

NO. DATE 1 8/12/22 2 11/17/22 Design Development Issued for Bid

G001



Existing to Remain

#### Finegold Alexander Architects

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08 ISSUE DATE: 11/17/22 PROJECT #.

ISSUE DATE: 11/17/22

PROJECT STATUS: Construction Dor

PAWN BY: Author


Charker DRAWN BY: Author
CHECKED BY: Checker SHEET NAME:

Demo Site Plan

DRAWING HISTORY:

**AD100** 

Demo Site Plan 1/8" = 1'-0"



PROJECT TEAM:

**(III**)

795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

Arup 60 State St, Boston, MA 02109

KEY PLAN:

PROJECT INFORMATION: Cambridge - City Hall Facade

Restoration

PROJECT #: P0128.08 ISSUE DATE: 11/17/22 PROJECT STATUS: Construction Documen CHECKED BY:

Demo Elevations


DRAWING HISTORY:


 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development

 2
 11/17/22
 Issued for Bid

AD200





City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope SImpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

**(** 

SEAL:



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Documents DRAWN BY: Author

CHECKED BY: Checker SHEET NAME:

Demo Elevations

DRAWING HISTORY:

 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development

 2
 11/17/22
 Issued for Bid


AD202

Legend - Demo Remove Element, Protect Existing Building and Repair Any Damage Caused by Removal, Leave Associated Surfaces Free and Clear for Installation of New Elements. Remove Existing Roofing, Protect Existing Building and Repair Any Damage Caused by Removal. Leave Associated Surfaces Free and Clear for Installation of New Roofing. Existing to Remain

Remove Element Carefully for Restoration and Reinstallation.

General Notes - Demo

Gnaphic indications of work specified on drawings are intended to give location of repair and approximate size of repair only, Drawings are two dimensional and all surfaces are not represented. All work should be field verified.
 Protect existing building and repair any surfaces dramaged in process of removal of indicated elements.
 Refer to EN series sheets for demo associated with masonry repair scope.
 A. Existing Windrows, Roofing, Snow Rails, Hatches, Stone and Metal Detailing, Scuppers and Downspouts to Remain Unless Indicated.



Key Plan 1/32" = 1'-0"

Finegold Alexander Architects

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction
DRAWN BY: Author CHECKED BY: Checker SHEET NAME:

Demo Elevations

DRAWING HISTORY:

 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development

 2
 11/17/22
 Issued for Bid

AD203



THIRD FLOOR
EL. 77.16'

→ ATTIC EL. 89,16'

TOP OF RIDGE


SECOND FLOOR
EL. 62.83

FIRST FLOOR

BASEMENT
EL. 36.27'

1 East Demo Elevation - Rear Court

2 West Demo Elevation - Rear Court



PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN:

SEAL:



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Docume

CHECKED BY: SHEET NAME:

Demo Elevations

DRAWING HISTORY:

NO. DATE DESCRIPTION

1 8/12/22 Design Development

2 11/17/22 Issued for Bid

AD204

Legend - Demo Remove Element, Protect Existing Building and Repair Any Damage Caused by Removal. Leave Associated Surfaces Free and Clear for Installation of New Elements. Remove Element Carefully for Restoration and Reinstallation,

> - Remove Existing Flashing - Remove Existing Membrane

Remove Any Existing Insulation, Waterproofing and Underlayments

Remove Any Existing Sheathing and Blocking to Stone Surface Existing Stone Masonry
 Balcony Surface
 Existing Stone Sill General Notes - Demo

Graphic indications of work specified on drawings are intended to give location of repair and approximate size of repair only. Drawings are two dimensional and all surfaces are not represented. All work should be field verified.
 Protect existing building and repair any surfaces damaged in process of removal of indicated elements.
 Refer to EN series sheets for demo associated with masony repair scope.
 Existing Windows, Roofing, Snow Rails, Hatches, Stone and Metal Detailing, Scuppers and Downspouts to Remain Unless Indicated.

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139


Finegold Alexander Architects

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451 House Doctor


Arup 60 State St, Boston, MA 02109

Remove Existing Flashing Remove Existing Membrane Remove Any Existing Insulation, Waterproofing, and Underlayments Remove Any Existing Sheathing and Blocking to Stone Surface

3 Balcony Demo Section at Existing Roof



2 Flagpole Strut Through-Bolt Connection Demo Detail



1 Balcony Demo Plan 1/2" = 1'-0"



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration

ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Doc
DRAWN BY: Author CHECKED BY: Checker

SHEET NAME: Demo Details


DRAWING HISTORY:

 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development

 2
 11/17/22
 Issued for Bid

AD500



PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN:



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Doc
DRAWN BY:


CHECKED BY:

SHEET NAME: Site Plan

NO. DATE 
 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development

 2
 11/17/22
 Issued for Bid



PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

House Doctor Arup 60 State St, Boston, MA 02109



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction

Site Logistics Plan

A101

1 Site Logistics Plan N.T.S.

Legend - Bird Deterrents BD2 Install New Mesh Bird Deterrent BD3 ///// Refer to EN-series sheets for bird deterrent fastening to mason MInstall New Bird Deterrent Per Specification. BD2 ------2 A501 TOP OF RIDGE ◆ ATTIC EL. 89.16' THIRD FLOOR Replace 10% of Glazing Putty at Existing Windows. Final Quantities TBD by Architect and Engineer in Field, Refer to Specification Section 064400. SECOND FLOOR
EL. 62.83' A  $\bigcirc$  $\bigcirc$  $\bigcirc$  $\bigcirc$ A  $\bigcirc$ A  $\bigcirc$ FIRST FLOOR
EL. 47.50' H  $\Theta$ H H H  $\Theta$ BASEMENT EL. 36,27'

General Notes

General Notes

1. Graphic indications of work specified on drawings are intended to give location of repair and approximate size of repair only. Drawings are two dimensional and all surfaces are not represented. All work should be field verified.


2. Clean all gliding areas and inspect for poorly bonded gold leaf prior to application, Repair and clean metal elements to be gidded. Refer to specification section 099133.

3. Repaint elements per manufacturer instructions, with finish coat color to match existing. Refer to specification section 099133.

4. Protect existing building and repair any elements damaged in process of gidding, painting, clock restoration, and vindow restoration work. Refer to project specifications.

5. Refer to EN-series sheets for masonry scope.

6. 70% of every window to receive wood epoxy restoration, 10% of every window to receive wood dutchman repair. GC to carry unit cost for wood repairs. Selected contractor to perform a repair quantify survey in advance of work and provide quantities as submittal for Architect's review to determine final quantities.



Key Plan 1/32" = 1'-0"

Finegold Alexander Architects

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN

PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration

PROJECT #:

ISSUE DATE: 11/17/22
PROJECT STATUS: Construction D
DRAWN BY:

SHEET NAME: Exterior Elevations

DRAWING HISTORY:

CHECKED BY:


DESCRIPTION

Design Develop

Issued for Bid

**A200** 

1) South Elevation - Massachusetts Ave.



OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451


Arup 60 State St, Boston, MA 02109

Cambridge - City Hall Facade

PROJECT #: P0128.08 ISSUE DATE: 11/17/22 PROJECT STATUS: Construction Docu

Exterior Elevations

DESCRIPTION



PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor
Arup
60 State St, Boston, MA 02109

KEY PLAN:

CONSTRUCTION

CONSTRUCTION

PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration

795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Docume

CHECKED BY: SHEET NAME:

Exterior Elevations

DRAWING HISTORY:

 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development

 2
 11/17/22
 Issued for Bid

Legend - Bird Deterrents

BD1 Install New Net Bird Deterrent



Install New Mesh Bird Deterrent



Refer to EN-series sheets for bird deterrent fastening to masonry

General Notes

General Notes

1. Graphic indications of work specified on drawings are intended to give location of repair and approximate size of repair only. Drawings are two dimensional and all surfaces are not represented. All work should be field verified.


2. Clean all gliding areas and inspect for poorly bonded gold leaf prior to application. Repair and clean metal elements to be gidded. Refer to specification section 099133.

3. Repaint elements per manufacturer instructions, with finish coat color to match existing. Refer to specification section 099133.

4. Protect existing building and repair any elements damaged in process of gilding, painting, clock restoration, and window restoration work. Refer to project specifications.

5. Refer to ENt-series sheets for masonry scope.

6. 70% of every window to receive wood epoxy restoration, 10% of every window to receive wood dutchman repair. GC to carry unit cost for wood repairs. Selected contractor to perform a repair grainty survey in advance of work and provide quantities as submittal for Architect's review to determine final quantities.



Key Plan 1/32" = 1'-0"

KEY PLAN:



Finegold Alexander Architects

795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

Arup 60 State St, Boston, MA 02109

PROJECT TEAM:

OWNER: City of Cambridge

House Doctor

PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08 ISSUE DATE: 11/17/22 ISSUE DATE: PROJECT STATUS: Construction Doc

CHECKED BY: SHEET NAME:


Exterior Elevations


DRAWING HISTORY:

 
 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Develog

 2
 11/17/22
 Issued for Bid
 DESCRIPTION





PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor
Arup
60 State St, Boston, MA 02109

0.000000,000000,000000

KEY PLAN:

SEAL



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration

795 Massachusetts Ave. Cambridge, MA 0213

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Docu
DRAWN BY:
CHECKED BY:

SHEET NAME:
Exterior Elevations

DRAWING HISTORY:

 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development


 2
 11/17/22
 Issued for Bid

SHEET#:

2c. Provide Borate Fungicide Rods at Areas of Removed Deteriorated Wood Step 3

- Existing Wood Frame, Profile Varies

3 Section Detail - Typ. Wood Epoxy Repair \_\_\_\_\_



2 Section Detail - Typ. Wood Dutchman Repair

General Notes

Existing Stone Header

- Glazing Tack

Existing Stone Sill

1 Section Detail - Typ. Glazing Putty Replacement 3" = 1-0"

Remove and Replace Caulking, Typ.
Glazing Putty; Remove and Replace,
Slope to Feather Edge. Ref. to
Specification Section 064400.

- Existing Monolithic Glass Pane. Extend Paint Onto Edge of Glass, Covering Putty Completely.

- Glazing Putty; Remove and Replace, Slope to Feather Edge. Ref. to Specification Section 064400.

- Existing Wood Frame, Profile Varies Wood Trim, Prepare and Paint, Typ. Ref. to Specification Section 064400.

Remove and Replace Caulking, Typ.

General Notes

1. Graphic indications of work specified on drawings are intended to give location of repair and approximate size of repair only. Drawings are two dimensional and all surfaces are not represented. All work should be field verifed.

2. Clean all gliding areas and inspect for poorly bonded gold leaf prior to application. Repair and clean metal elements be manufacture instructions, with finish coat color to match existing. Refer to specification section 099133.

3. Repaint elements per manufacture instructions, with finish coat color to match existing. Refer to specification section 099130.

4. Protect existing publiding and repair any elements damaged in process of gilding, painting, clock restoration, and window restoration work. Refer to project specifications.

5. Refer to EN-series sheets for masonry scope.

6. 70% of every window to receive wood epoxy restoration, 10% of every window to receive wood dutchman repair. GC to carry unit cost for wood repairs. Selected contracts to perform a repair quantify survey in advance of work and provide quantifies as submittal for Architect's review to determine final quantities.

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

Finegold Alexander Architects

House Doctor

Arup 60 State St, Boston, MA 02109

SEAL:



PROJECT INFORMATION: Cambridge - City Hall Facade

Restoration 795 Massachusetts Ave. Cambridge, MA 02139

11/17/22 ISSUE DATE: PROJECT STATUS: Construction Do DRAWN BY: Author
CHECKED BY: Checker

SHEET NAME: Window Details


DRAWING HISTORY: 
 NO.
 DATE
 DESCRIPTION

 1
 8/12/22
 Design Development


 2
 11/17/22
 Issued for Bid

Specialty Clock Technician to Carefully Remove All-Clock Hands, Clock Numbers, Second Markers, and Mounting Hardware. Clock Technician to Hand Over Clock Hands, Clock Numbers, Second Markers, and Hardware to Specialty Gliding Contractor Retained by the Painting Contractor for Restoration of Ornamental Metal and Gliding, Once Gliding is Complete, Gilding Contractor to Hand Over the Clock Hands, Clock Numbers, Second Markers, and Hardware for Re-Installation by Specialty Clock Technician. Painter to Touch Up Paint, Repair Damage, and Restore Finish at Clock Face, Typ.





2 Typical Clock Elevation



#### General Notes

General Notes

1. Graphic indications of work specified on drawings are intended to give location of repair and approximate size of repair only. Drawings are two dimensional and all surfaces are not represented. All work should be field verified.

2. Clean all gliding areas and inspect for poorly bonded gold leaf prior to application. Repair and clean metal elements to be gilded. Refer to specification section 099133.

3. Repaint elements per manufacturer instructions, with finish coat color for match existing. Refer to specification section 099133.

4. Protect existing building and repair any elements damaged in process of gilding, painting, clock restoration, and window restoration work. Refer to project specifications.

5. Refer to EN-series sheets for masorny scope.

6. 70% of every window to receive wood epoxy restoration, 10% of every window to receive wood dutchman repair. GC to carry unit cost for wood repairs. Selected contractor to perform a repair quantify survey in advance of work and provide quantities as submittal for Architect's review to determine final quantities.

#### Finegold Alexander Architects

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109



PROJECT INFORMATION:


Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139

PROJECT #: P0128.08
ISSUE DATE: 11/17/22
PROJECT STATUS: Construction Documents
DRAWN BY: Author
CHECKED BY: Checker

Ornamental Metal & Gilding Details

DRAWING HISTORY:


110.	DAIL	DECOMI HON
1	8/12/22	Design Development
2	11/17/22	Issued for Bid



General Notes

4 Balcony Section at New EPDM Roof

- Existing Flagpole and Attachment System to be Replaced with New Self-storing Flagpole, Base, Struts and Attachment Hardware. Refer to Structural Drawings and Specification Section 107500.




5 Flagpole Strut Through-Bolt Connection Repair Detail

3 Flagpole Strut Connector Plate

2 Balcony Elevation - Side

Cut Interior Finishes for Through-Bolt Installation. Patch and Repaint Following Installation to Match Existing Conditions.

New Through-Bolt Connection Strut, Strut Connector, and Hardware, Refer to Structural Drawings and Specification Section 107500.



1 Balcony Plan 1/2" = 1'-0"

### Finegold Alexander Architects

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

SEAL: PRESIMINARY CONSTRUCTION

PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 02139


P0128.08 11/17/22 ISSUE DATE: PROJECT STATUS: Construction D CHECKED BY: Checker SHEET NAME

Roofing & Flagpole Details

NO.	DATE	DESCRIPTION
1	8/12/22	Design Development
2	11/17/22	Issued for Bid
_		
_		

**A502** 

INTERIOR



- GENERAL NOTES
  1. GOVERNING CODE: MASSACHUSETTS STATE BUILDING CODE (780 CMR), 9TH EDITION.
  2. THE BUILDING WILL REMAIN OPEN DURING CONSTRUCTION AND THE MAIN ENTRY, EMERGENCY EXIT, AND FIRE DEPARTMENT WATER CONNECTION, MUST REMAIN UNOBSTRUCTED AND ACCESSIBLE AT ALL TIMES THROUGHOUT CONSTRUCTION, INFORMATION ON PERMISSIBLE WORK HOURS, STAGING AND STORAGE AREAS, AND OTHER LOGISTICAL QUESTIONS WILL BE DESIGNATED AT A PRE-CONSTRUCTION METING.
  4. THE BUILDING IS HISTORIC, AND ALL EXTERIOR WORK IS UBJECT TO REVIEW AND APPROVAL BY THE CITY OF CAMBRIDGE HISTORICAL COMMISSION. THE INTENT OF THE
- 4. THE BUILDING IS HISTORIC, AND ALL EXTERIOR WORK IS SUBJECT TO REVIEW AND APPROVAL BY THE CITY OF CAMBRIDGE HISTORICAL COMMISSION. THE INTERT OF THE WORK IS TO REPAIR THE FACADE IN-KIND, WITH MATERIALS THAT MATCH THE EXISTING HISTORIC MATERIALS AS CLOSELY AS POSSIBLE IN COMPOSITION, COLOR, TEXTURE, AND OVERALL APPEARANCE.

  5. ALL LOCATIONS INDICATED FOR REPAIR ARE APPROXIMATE AND BASED ON PRIOR SURVEY OF THE FACADE. THE FINAL, ACTUAL LOCATIONS AND QUANTITIES FOR REPAIR MAY BE MORE OR LESS THAN THOSE INDICATED IN THE TABLE AT RIGHT, AND WILL BE BASED ON HANDS-ON SURVEY BY THE CONTRACTOR AND SUBMITTED WITH THE MASONRY REPAIR SHOP DRAWINGS FOR APPROVAL BY THE ENGINEER.

  6. ALL MATERIALS INDICATED ON THESE DRAWINGS ARE NEW, UNLESS SPECIFICALLY NOTED AS EXISTING.

- 6. ALL MATERIALS INDICATED ON THESE DRAWINGS ARE NEW, UNLESS SPECIFICALLY NOTED AS EXISTING.
  7. ALL EXISTING BUILDING DIMENSIONS, WHERE PROVIDED, ARE APPROXIMATE AND SHALL BE VERIFIED BY THE CONTRACTOR IN THE FIELD. NOTIFY THE ENGINEER OF ANY INCONSISTENCIES THAT AFFECT THE WORK WITH SUFFICIENT TIME TO PREVENT DELAY OF THE WORK.

  8. TEST FOR HAZARDOUS MATERIALS, OBTAIN PROPER PERMITS AND FOLLOW ALL REQUIRED PROCEDURES FOR WORKING WITH, REMOVAL, AND DISPOSAL OF HAZARDOUS MATERIALS.

- OVERVIEW SUMMARY SCOPE OF WORK
  THIS OVERVIEW SUMMARY SCOPE OF WORK IS PROVIDED FOR THE CONVENIENCE
  OF THE CONTRACTOR, AS AN INTRODUCTORY OVERVIEW TO THE FULL SCOPE OF
  WORK DESCRIBED IN THE DRAWINGS AND SPECIFICATIONS. THOROUGHLY
  SUMMARY, FOR THE FULL SCOPE OF WORK.

  1. COORDINATE WITH THE CITY OF CAMBRIDGE AND OBTAIN ALL PERMITS
  NECESSARY FOR THE WORK.

  2. MOBILIZE THE SITE AND PROOF ANY AND ALL EQUIPMENT NECESSARY TO
  ACCESS THE FACADE WITH PROVIDE ANY AND ALL EQUIPMENT NECESSARY TO
  ACCESS THE FACADE WITH PROVIDE ANY AND ALL EQUIPMENT NECESSARY TO
  ACCESS THE FACADE WITH PROVIDE ANY AND ALL EQUIPMENT NECESSARY TO
  ACCESS THE FACADE WITH PROVIDE ANY AND ALL EQUIPMENT NECESSARY TO
  ACCESS THE FACADE
  THROUGHOUT CONSTRUCTION INCLUDING ACCESS TO WHATEVER MEANS ARE
  USED BY THE CONTRACTOR TO ACCESS THE FACADE AND ROOF (E.G.,
  SCAFFOLD, AERAL LIFTS, ETC.),
  4. COMPLETE MULTIPLE ROUNDS OF MOCKUPS PER THE SPECIFICATIONS TO
  DEVELOP MASONRY CLEANING AND REPAIRS CLEANING MUST EFFECTIVELY
  CLEAN BUT NOT DAMAGE THE EXISTING MASONRY, FOR REVIEW AND
  APPROVAL BY CITY OF CAMBRIDGE AND ENGINEER. MASONRY REPAIRS MUST
  MATCH THE SURROUNDING EXISTING MASONRY, DO NOT PROCEED WITH
  MASONRY REPAIRS, OR CLEANING MOCKUPS BY THE CITY OF CAMBRIDGE AND
  ENGINEER. UNDERTAKE LOCALIZED CLEANING WHERE INDICATED.
  APPEROVAL DY THE CLEANING MOCKUPS BY THE CITY OF CAMBRIDGE
  AND ENGINEER.
  APER APPROVAL OF THE CLEANING MOCKUPS BY THE CITY OF CAMBRIDGE
  AND ENGINEER.
  APER PROVAL OF THE CLEANING MOCKUPS BY THE CITY OF CAMBRIDGE
  AND ENGINEER.
  APER APPROVAL OF THE CLEANING MOCKUPS BY THE CITY OF CAMBRIDGE
  AND ENGINEER.
  APER APPROVAL OF CAMBRIDGE AND ENGINEER.

  APER PROVAL OF CAMBRIDGE AND ENGINEER.

  APER PROVAL OF CAMBRIDGE AND ENGINEER.

  APER PROVAL OF CAMBRIDGE AND ENGINEER.

  A PERFORM LOCALIZED REPAIRS AT THE BROWNSTONE AND GRANITE
  MASONRY.

  B. PERFORM LOCALIZED REPAIRS OF THE CONCRETE.

  D. PERFORM LOCALIZED REPAIRS OF THE CONCRETE.

  D. PERFORM BLOCALIZED REPAIRS OF THE CONCRETE.

  D. PERFORM GENERAL CLEANING.
  COMPLETE ALL PUNCHLIST ITEMS PRIOT OT DEMOBILIZING FR

	g 8		QUA	QUANTITY		
ITEM NO. (SEE ELEVATIONS)	REPAIR TYPE	DETAIL	TOTAL FOR BASE BID	UNITS		
EN1	STONE REPAIR AT CRUCIFORM	1/EN300	5	EA		
EN2	STONE REPAIR AT VERTICAL MULLION	2/EN300	25	EA		
EN3	TYPICAL FERROUS ANCHOR TREATMENT	3/EN300	150	EA		
EN4	TYPICAL COPING AND PINNACLE REPAIR	1/EN301	10	EA		
EN5	SIDE PINNACLE REPAIR - PLAN AND PHOTO	2/EN301	10	EA		
EN6 CRACK REPAIR AT SPANNING STONE - ELEVATION		3/EN301	10	EA		
EN7 '	' TYPICAL REPOINTING 4/EN301 1		10%	SF		
EN8	TYPICAL CRACK REPAIR AT FULLY SUPPORTED STONE - SECTION	1/EN302	150	LF		
EN9	TYPICAL STONE REPAIR WITH REPAIR MORTAR - SECTION	2/EN302	8	EA		
EN10	TYPICAL STONE REPAIR AT ABANDONED FASTENER OR HOLE	3/EN302	10	EA		
EN11	TYPICAL STONE REPAIR WITH DUTCHMAN - SECTION	4/EN302	8	EA		
EN12	TYPICAL WHOLE STONE REPLACEMENT - SECTION	5/EN302	5	EA		

A SUMMARY OF THE QUANTITIES TO BE CARRIED IN THE BASE BID IS INCLUDED IN THE TABLE ABOVE. BID THE QUANTITIES IN THE TABLE, DO NOT TAKE-OFF QUANTITIES FROM ELEVATION SHEETS.

### Finegold Alexander Architects

PROJECT TEAM:

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN



CAMBRIDGE - CITY HALL FACADE

PROJECT#: 211204 ISSUE DATE: 11/17/2022
PROJECT STATUS: 100% CONSTRUCTION DRAWINGS

DRAWN BY: SKW/ESV CHECKED BY: EML/MBB

SHEET NAME: GENERAL NOTES

DRAWING HISTORY:

NO. DATE DESCRIPTION

EN001

PROJECT TEAM:

OWNER:


City of Cambridge 795 Massachusetts Ave, Cambridge

Structural & Envelope
Simpson Gumpertz & Heger

House Doctor

Arup 60 State St, Boston, MA 02109

KEY PLAN



SFAI.



CAMBRIDGE - CITY HALL FACADE

PROJECT #: 211204
ISSUE DATE: 11/17/2022
PROJECT STATUS: 100% CONSTRUCTION DRAWINGS
DRAWN BY: SKW/ESV
CHECKED BY: EMIJ/MBB
SHEET INME:


SOUTH ELEVATION - MASONRY REPAIRS

DRAWING HISTORY:

NO. DATE DESCRIPTION

EN200

35:37 PM




PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, N

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109





PROJECT INFORMATION:

CAMBRIDGE - CITY HALL FACADE

PROJECT #: 211204
ISSUE DATE: 11/17/2022
PROJECT STATUS: 100% CONSTRUCTION DRAWINGS
DRAWN BY: SKWIESV
CHECKED BY: EMUMBB
SHEET INME:

EAST ELEVATION - MASONRY REPAIRS

DRAWING HISTORY:

NO. DATE DESCRIPTION

EN201

PROJECT TEAM:

OWNER: City of Ca


City of Cambridge 795 Massachusetts Ave, Cambridge, M

Structural & Envelope
Simpson Gumpertz & Heger
480 Totten Pond Rd Waltham MA 024

House Doctor

Arup 60 State St, Boston, MA 02109

KEY PL



SFAI.



CAMBRIDGE - CITY HALL FACADE

CAMBRIDGE - OTT TIALLT ACAD

PROJECT #: 211204
ISSUE DATE: 11/17/2022
PROJECT STATUS; 100% CONSTRUCTION DRAWINGS
DRAWN BY: SKW/ESV.
CHECKED BY: EMUMBB

SHEET NAME:


NORTH ELEVATION - MASONRY REPAIRS

DRAWING HISTO

NO: DATE DESCRIPTION

EN202

\Documents\211204\_Cambridge City Hall\_R22\_BT\_esven




PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope
Simpson Gumpertz & Heger
480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN



SEA



PROJECT INFORMATION:

CAMBRIDGE - CITY HALL FACADE

PROJECT #: 211204
ISSUE DATE: 11/17/2022
PROJECT STATUS: 100% CONSTRUCTION DRAWINGS
DRAWN BY: SKWESV
CHECKED BY: EML/MBB
SHEET NAME:


WEST ELEVATION - MASONRY REPAIRS


NO. DATE

). DATE DESCRIPTION

EN203

KEYNOTE ELEVATION LEGEND				
Key Value	Key Value Keynote Text			
EN1	STONE REPAIR AT CRUCIFORM, SEE 1/EN300			
EN2	STONE REPAIR AT VERTICAL MULLION, SEE 2/EN300			
EN3	TYPICAL FERROUS ANCHOR TREATMENT, SEE 3/EN300			
EN4	TYPICAL COPING AND PINNACLE REPAIR, SEE 1/EN301			
EN5	SIDE PINNACLE REPAIR - PLAN AND PHOTO, SEE 2/EN301			
EN6	CRACK REPAIR AT SPANNING STONE - ELEVATION, SEE 3/EN301			
EN7	TYPICAL REPOINTING, SEE 4/EN301			
EN8	TYPICAL CRACK REPAIR AT FULLY SUPPORTED STONE - SECTION, SEE 1/EN302			
EN9	TYPICAL STONE REPAIR WITH REPAIR MORTAR - SECTION, SEE 2/EN302			
EN10	TYPICAL STONE REPAIR AT ABANDONED FASTENER OR HOLE, SEE 3/EN302			
EN11	TYPICAL STONE REPAIR WITH DUTCHMAN - SECTION, SEE 4/EN302			
EN12	TYPICAL WHOLE STONE REPLACEMENT - SECTION, SEE 5/EN302			
EN13	TYPICAL STONE SURFACE REDRESSING - SECTION, SEE 6/EN302			





WEST COURTYARD ELEVATION

1/8" = 1'-0"

EAST COURTYARD ELEVATION

1/8" = 1"-0"

# GENERAL NOTES

- Repair locations are approximate and quantities are estimated from limited survey and may not include all required repairs. Contractor to provide base bid from quantities shown in these dravings and unit price cost as outlined in the Project Specifications. Selected contractor to perform a repair quantity survey in advance of the work and provide quantities and shop dravings as submittal for Engineer's review.

  Clean stone prior to submitting samples for color matching and performing mockups.


  For window repairs, painting, gilding, and bird protection refer to Architectural Dravings.

## Finegold Alexander Architects

PROJECT TEAM:

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

Arup 60 State St, Boston, MA 02109





CAMBRIDGE - CITY HALL FACADE

 PROJECT #:
 211204

 ISSUE DATE:
 11/17/2022

 PROJECT STATUS:
 100% CONSTRUCTION DRAWINGS

 DRAWN BY:
 SKWIESV


 CHECKED BY:
 EML/MBB

SHEET NAME:

COURTYARD ELEVATIONS -MASONRY REPAIRS

NO. DATE DESCRIPTION

EN204



- (E) VERTICAL STONE TO REMAIN ROUND HOLE, DO NOT OVERDRILL STONE DUTCHMAN -GROUT JOINT SOLID. POINT MORTAR JOINT TO MATCH (E) MORTAR COLOR AND PROFILE, SEE 4/EN301 - FULLY BED INTERFACE WITH EPOXY; DUST EXPOSED SURFACE OF WET EPOXY WITH STONE DUST FROM DRILL HOLES, SEE 4/EN302 NOTE

1. DUTCHMAN DIMENSIONS VARY BASED ON EXISTING CONDITIONS, VERIFY ALL DIMENSIONS IN THE FIELD.

2. DRILL HOLES AND LOCATE SPRING PINS WHERE INDICATED

3. USE SHEET METAL TOOL TO COMPRESS SPRING PINS, DRY FIT DUTCHMAN FLUSH WITH ADJACENT (E) BROWNISTOME, MARK LOCATIONS ON SIDE FOR DRILLING SPRING PIN HOLES PRIOR TO INSTALLATION.


1B - DUTCHMAN INSTALLATION

- TOP STONE MORTAR JOINT 4"LONG, 38" Ø S.S. DROP FIN, TYP

1C - DROP PIN

1A - DEMOLITION

STONE REPAIR AT CRUCIFORM



2A - PREP

FULLY BED INTERFACE -WITH EPOXY; DUST EXPOSED SURFACE OF WET EPOXY WITH STONE DUST FROM DRILL HOLES, SEE 4/EN302. - ROUND HOLE, 3 1/2" DEEP, TYP. DO NOT OVERDRILL 4" LONG, 3/8" DIAM. SS DROP PIN. STONE DUTCHMAN - GROUT JOINT SOLID, POINT MORTAR JOINT TO MATCH (E) MORTAR COLOR AND PROFILE, SEE 4/EN301 - (E) BROWNSTONE

- 4" LONG, 3/8" DIAM. SS DROP PIN, SEE 1C, TYP.

NOTE:

1. DUTCHMAN DIMENSIONS VARY BASED ON EXISTING CONDITIONS. VERIFY ALL DIMENSIONS IN THE FIELD.

2. DRILL HOLES, LOCATE DROP PINS WHERE INDICATED SOLUTION OF THE PROPERTY OF THE DUTCHMAN FLUSH WITH ADJACENT (E): BROWNSTONE. MARK LOCATIONS ON SIDE FOR DRILLING DROP PIN HOLES PRIOR TO INSTALLATION

2B - DUTCHMAN INSTALLATION

TYPICAL FERROUS ANCHOR TREATMENT
3'=1'0'

(E) FERROUS ANCHOR TO REMAIN

INTERIOR

(E) STONE

Finegold Alexander Architects

City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN:



CAMBRIDGE - CITY HALL FACADE

PROJECT#: 211204 ISSUE DATE: 11/17/2022
PROJECT STATUS: 100% CONSTRUCTION DRAWINGS DRAWN BY: SKWIESV EML/MBB SHEET NAME:

BROWNSTONE MASONRY REPAIR DETAILS

- STEP 1:

REMOVE MORTAR TO SOUND MORTAR OR MINIMUM DEPTH OF 3 IN., WHICHEVER IS GREATER

EXTERIOR


- STEP 2: AFTER 3" DEEP MORTAR REMOVAL APPLY CORROSION-INHIBITING COATING; TO SATURATE (E) SOUND MORTAR


STEP 3: REPOINT MORTAR JOINT (SEE DETAIL 4/EN301)

NO. DATE DESCRIPTION

EN300

STONE REPAIR AT VERTICAL MULLION 2 STON





2A - PLAN




- DRILL AND INSTALL (4) 1/4" DIA. X 24 IN.
MIN. LENGTH S.S. HELIFIX ANCHOR
RODS HORIZONTALLY THROUGH
PINNACLE INTO ADJACENT STONES
WITH MIN. 12 IN. EMBEDMENT, RECES
HEAD OF ANCHOR MINIMUM "FROM
FACE OF EXPOSED STONE AND INSTALL
BROWNISTONE REPAIR MORTAR AT
ANCHOR ROD LOCATIONS

<u> 2B - PHOTO</u>

TYPICAL COPING AND PINNACLE REPAIR

SIDE PINNACLE REPAIR - PLAN AND PHOTO



AT DECORATIVE BROWNSTONE ARCHES AT MAIN ENTRANCE ON SOUTH ELEVATION

(E) SPANNING STONE (E.G. LINTEL OR HORIZONTAL MULLION) - CONCEALED STAINLESS STEEL/EPOXY ANCHORS SET IN EPOXY AT MID-WIDTH OF STONE (MID-WAY "INTO PAGE" AS DRAWN)

NOTES:

1. PRIOR TO STARTING REPAIR, PROVIDE ENGINEER WITH ANNOTATED PHOTOS SHOWING DIMENSIONS OF STONE, SO ENGINEER CAN SPECIFY MINIMUM EMBEDMENT LENGTH, MINIMUM DOWEL DIAMETER, NUMBER OF RODS REQUIRED, AND ANGLE OF ROD.

2. INSTALL STANLESS STEEL ROD ANCHORS SET IN EPOXY, INSTALLED PERPENDICULAR TO CRACK AT MID-WIDTH OF STONE, TWO MINIMUM PER MEMBER, RECESS HEAD OF ANCHOR MIN 1" FROM EXPOSED STOONE.

3. CLEAN CRACK WITH COMPRESSED AIR. INJECT CRACK WITH NON-STAINING EPOXY TINTED TO MATCH COLOR OF STONE, APPLY STONE DUST FROM DRILL HOLE TO SURFACE OF EPOXY WHEN WET.

4. PATCH EXPOSED HOLE AT DRILL POINT WITH REPAIR MORTAR.

CRACK REPAIR AT SPANNING STONE - ELEVATION (3)

Finegold Alexander Architects

Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham, MA 02451

Arup 60 State St, Boston, MA 02109

CAMBRIDGE - CITY HALL FACADE

PROJECT#: 211204 ISSUE DATE: 11/17/2022
PROJECT STATUS: 100% CONSTRUCTION DRAWINGS DRAWN BY: SKW/ESV


CHECKED BY: EML/MBB SHEET NAME:

MASONRY REPAIR DETAILS

DRAWING HISTORY: NO. DATE DESCRIPTION

**EN301** 

TYPICAL REPOINTING




NOTES:
1. ONLY REPAIR CRACK IF > 1/16" WIDE.
2. CLEAN CRACK WITH COMPRESSED AIR AND TEST TUBE BRUSH.
3. POINT CRACK WITH BROWNISTONE REPAIR MORTAR TO MINIMUM DEPTH OF 2 1/2 x CRACK WIDTH.
4. TOOL TO MATCH PROPILE AND TEXTURE OF SURROUNDING BROWNISTONE.
5. TYPICAL CRACK REPAIR AT FULLY SUPPORTED STONE. SEE 2/EN301 FOR CRACKS IN SPANNING STONES, SUCH AS LINTELS, CORBELS, OR ARCH STONES.

TYPICAL CRACK REPAIR AT FULLY SUPPORTED STONE - SECTION
3"=1'-0"

PROFILE OF (E) BROWNSTONE VARIES INTERIOR EXTERIOR S.S. PAN HEAD MASONRY SCREW; TWO PER REPAIR, MIN., WITH ONE PER EVERY 20 SQ. IN. OF REPAIR SURFACE AREA MINIMUM, WHICHEVER IS GREATER. PROVIDE 3/4" MIN. COVER ON FASTENER HEADS AND WIRE AND PROVIDE 3/4" MIN. EXPOSE CANTILEVER ON - (E) BROWNSTONE

TYPICAL STONE REPAIR WITH REPAIR MORTAR - SECTION



TYPICAL STONE REPAIR AT ABANDONED FASTENER OR HOLE

PROFILE OF (E) BROWNSTONE VARIES INTERIOR **EXTERIOR** REPOINTED MORTAR JOINT, INSTALL STONE DUTCHMAN PRIOR TO REPOINTING SQUARE-OFF (E) SPALL, REMOVING ALL DETERIORATING AND SCALING STONE TO MIN. OF 3'4" BEYOND DETERIORATED STONE 3/16"Ø SS THREADED ROD SET IN EPOXY; 1 PER SF OR TWO PER PATCH, MIN., WHICHEVER IS GREATER FULLY BED INTERFACE WITH EPOXY REPLACEMENT BROWNSTONE "DUTCHMAN", SURFACE PROFILE/FINISH TO MATCH (E) (E) LIMIT OF DETERIORATION 1" MIN 3/4" MIN V. W. W. W. W. W. W. DUST EXPOSED FACE OF WET EPOXY WITH STONE DUST FROM DRILL HOLES PROTECT AD IACENT SURFACES FROM EPOXY SMEARS AND STAINING MIN DEEP SQUAR CUT AT PERIMETER

TYPICAL STONE REPAIR WITH DUTCHMAN - SECTION (4)

REMOVE MORTAR JOINTS -AT ALL SIDES, AND COLLAR JOINT AT REAR OF STONE. DO NOT OVER-CUT JOINTS (E) PROFILE OF (E) ERODED STONE PROFILE OF -SS ANCHORS AT 16" OC REPLACEMENT STONETO MATCH **EXTERIOR** INTERIOR REMOVE (E) DEEPLY ERODED
BROWNISTONE AND RETAIN FOR
POTENTIAL USE IN DUCTHMAN
REPAIRS, REPLACE WITH NEW
BROWNISTONE IN FULL BED OF
MORTAR AT ALL SIDES AND
REAR; MATCH DEPTH,
DIMENSIONS, PROFILE, TEXTURE
OF (E) SURROUNDING, NONERODED STONE NOTE:

1. PROVIDE TEMPORARY SUPPORT OR SHORING OF MASONRY ABOVE BROWNSTONE TO BE REMOVED AS NECESSARY.

(3)

TYPICAL WHOLE STONE REPLACEMENT - SECTION (5) 1 YPI

(E) PROFILE OF (E) ERODED STONE **EXTERIOR** (E) LOOSE, SPALLING OR ERODED STONE MATERIAL "REDRESS" (RESURFACE BY HAND "REDRESS" (RESURFACE BY HAND CHISELING) STONE SURFACE TO REMOVE ALL LOOSE, SPALLING, OR REODED STONE TO CREATE A NEW, SOUND SURFACE WITH PROFILE TO MATCH THE ORIGINAL "ROCK-FACED" STONE SURFACE

TYPICAL STONE SURFACE REDRESSING - SECTION (6)

Finegold Alexander Architects

PROJECT TEAM:

City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope
Simpson Gumpertz & Heger
480 Totten Pond Rd, Waltham, MA 02451

Arup 60 State St, Boston, MA 02109

PROJECT INFORMATION CAMBRIDGE - CITY HALL FACADE

ISSUE DATE: 11/17/2022 PROJECT STATUS: 100% CONSTRUCTION DRAWINGS SKW/ESV EML/MBB CHECKED BY: SHEET NAME:

BROWNSTONE MASONRY REPAIR

DETAILS

NO. DATE DESCRIPTION

**EN302** 

#### GENERAL

- 1. The intent of the structural drawings is to show the main structural features and design for the completed project. Architectural details and other components that may be necessary to construct the project are shown incidentally only, and not completely; therefore the contractor must use all contract drawings and specifications in conjunction with the structural drawings during all phases of construction. Discrepancies between structural drawings, in for draiffed in the addenda at the request of the Contractor, shall be brought to the attention of the Architect/Engineer of Record (EOR) during construction for clarifications. The Contractor shall take this into consideration in their bid.
- Unless otherwise noted, details, sections and notes contained in the structural contract documents are typical for all similar conditions even if not explicitly referenced.
- Contractor shall not scale drawings to obtain any missing information or to interpret any information not specifically dimensioned for exact detailing or construction purposes.
- Deficient work and/or work not in conformance with the contract documents shall be repaired at the contractor's expense. The contractor shall compensate the client for services arising from deficient work, review of modifications/contractor substitution, or expediting of submittals.
- Cost of investigation and/or redesign incurred by the EOR due to contractor errors will be at the contractor's expense.
- The contractor shall submit a single dimensioned and coordinated drawing for each area of
  work incorporating work of a multiple subcontractors as required for review by the EOR. If
  work is not coordinated on the shop drawings, this will be a reason for the EOR to reject the
  submittal.
- Loads imposed on the base building structure and temporary conditions intended to
  accommodate construction means and methods are not explicitly considered in this design.
  The contractor shall advise the EOR regarding construction loads and temporary conditions
  imposed on the building structure and shall compensate the EOR for reviewing these
  conditions.
- All work shall be continuously monitored and inspected by an independent testing agency, retained by the Owner. Submit all inspection reports to Architect/EOR for review.
- Contractor shall carefully check stability of all elements of the building before doing any work on existing structures. Brace or strengthen all portions of structure which may be weakened by removal of existing construction until new constructions in place. Contractor shall be responsible for the design of temporary bracing, shoring, and strengthening. Submit design and supporting calculations sealed by a Massachusetts Professional Engineer for review.
- Structural scope comprises the new structural components and details in the specific area
  of the existing building as designated in the structural drawings. The existing structure
  outside of the scope of work shown is not part of this project.
- The contractor shall be completely responsible for the safety of adjacent structures, property, their workers, and the public, as affected by the construction of this project.

#### SPECIFICATIONS

- The work of these drawings addresses structural information only. The structural documents include these S-series Drawings and General Notes.
- 2. Refer to project specifications for detailed requirements for material and workmanship.

#### ELEVATIONS AND DIMENSIONS

- All elevations and dimensions shown for new construction are for information only.
   Dimensions for construction are to be taken from the Architectural Drawlings. Field verify all elevations and dimensions before proceeding with construction.
- Existing Dimensions: Existing dimensions are taken from the reference plans and are to be verified in the field by the contractor, as appropriate, prior to fabrication of members. The contractor shall report any discrepancies to the Architect/Engineer prior to proceeding with work.

#### BUILDING CODE

- 1. International Building Code 2015 with Massachusetts Amendments (9th Edition).
- 2. International Existing Building Code 2015 with Massachusetts Amendments (9th Edition).
- 3 ASCE/SEL7-10. Minimum Design Loads for Buildings and Other Structures
- Additional codes for materials are in the appropriate sections that follow. See those sections for the applicable codes.

#### DESIGN LOADS

Dead Loads
 A. All permanent stationary construction

2.	Ice Load Parameters	
	A. Design Ice Thickness, t₄	2 inches
	B. Nominal Ice Thickness, t	0.75 inch
	C. Height Factor, fz	1.03
	D. Ice Load Importance Factor, I	1,25
	E. Topographic Factor, Kzt	1.00
3.	Wind on Ice-Covered Structures	
	<ul> <li>A. Basic Wind Speed (3 second gust), V</li> </ul>	50 mph
	B. Design Temperature	15°F
	C. Wind Importance Factor, Iw	1.00
	D. Design Wind Pressure (Flagpole)	3.87 psf
	E. Design Wind Pressure (Flag)	9,96 psf
4.	Seismic Load Parameters	
	A. Risk Category	III

С.	Design valid Flessule (Flag)	0.00 pai
Sei	smic Load Parameters	
A.	Risk Category	111
B.	Seismic Importance Factor, IE	1.25
C.	Spectral Response Acceleration, S,	0.216
D.	Spectral Response Acceleration, S <sub>1</sub>	0.069
E.	Site Class	D (assumed
F.	Spectral Response Coefficient, Sps	0.230
G.	Spectral Response Coefficient, Sp1	0.110
H.	Seismic Design Category	В
1.	Seismic Response Coefficient, Cs	0.189
J.	Response Modification Factor, R	1.50
K.	Seismic Force Resisting System	

	a. Ordinary Plain Masonry Shear Walls	
5.	Wind Load Parameters	
	<ul> <li>A. Basic Wind Speed (3 second gust), V</li> </ul>	139 mph
	B. Wind Importance Factor, Iw	1.00
	C. Wind Exposure	C
	D. Design Wind Pressure (Flagpole)	56 psf
	E. Design Wind Pressure (Flag)	33.2 \Area of Flag
	F. Design Wind Pressure (Components & Cladding)	See Table ·



Notes:

1. The "a" distance is equal to the minimum of 10% of the least horizontal distance or 0.4\*h, but not less than 3 ft or 4% of the least horizontal dimension.

2. Positive indicates pressure to the building surface, negative indicates ressure to the building surface.

3. h is the mean roof height.


4. Linear interpolation of table is not permitted see ASCE 7 for more information.

	Building Component and Cladding Wind Loads (PSF)									
Area (SF)	Zone 1 Positive	Zone 1 Negative	Zone 2 Positive	Zone 2 Negative	Zone 3 Positive	Zone 3 Negative	Zone 4 Positive	Zone 4 Negative	Zone 5 Positive	Zone 5 Negative
≤10	33	-52	33	-90	33	-135	54	-52	54	-96
50	26	49	26	-74	26	-114	50	-50	50	-84

#### MASONRY

- ADHESIVE ANCHORS
   A. Hill HIT HY-270. Install per Hill installation recommendations. Unless otherwise noted embed dowels 10 bar dameters.
- EXPANSION ANCHORS
   Hitl HLC Sleeve Anchors. Install per Hitl installation recommendations. Unless otherwise noted embed boits 10 bolt diameters.

ABBREVIATION	WORD OR PHRASE	ABBREVIATION	WORD OR PHRASE
&	AND	K	KIPS
@	AT	KSI	KIPS PER SQUARE INCH
ACI	AMERICAN CONCRETE INSTITUTE		
ADD'L	ADDITIONAL	LBS	POUNDS
AESS	ARCHITECTURAL EXPOSED	LL.	LIVE LOAD LONG LEG HORIZONTAL
AISC	STRUCTURAL STEEL AMERICAN INSTITUTE OF STEEL	LLH	LONG LEG HORIZONTAL LONG LEG VERTICAL
AISC	CONSTRUCTION	LONG	LONGITUDINAL
ALT	ALTERNATE	LONG	LONGITODINAL
APPROX	APPROXIMATE	MAX	MAXIMUM
ARCH	ARCHITECT	MECH	MECHANICAL
ASD	ALLOWABLE STRENGTH DESIGN	MIN	MINIMUM
ASTM	AMERICAN SOCIETY FOR	MISC	MISCELLANEOUS
	TESTING AND MATERIALS	MBC	MASSACHUSETTS BUILDING CODE
AWS	AMERICAN WELDING SOCIETY	MCR	MASSACHUSETTS CODE OF
			REGULATIONS
BLK'G	BLOCKING		
ВМ	BEAM	(N)	NEW
BOT	BOTTOM	NÓ, # NS	NUMBER NEAR SIDE
BRG	BEARING BETWEEN	NTS	NOT TO SCALE
BTW	BETAVEEN	NW	NORMAL WEIGHT
CC	CENTER TO CENTER	1444	NORMAL WEIGHT
CJ	CONTROL JOINT	OC	ON CENTER
CIP	CAST-IN-PLACE	OD	OUTSIDE DIAMETER
CL	CENTER LINE	OH	OPPOSITE HAND
CLR	CLEAR	OPNG	OPENING
CMU	CONCRETE MASONRY UNIT		
COL	COLUMN	PART	PARTIAL
CONC	CONCRETE	PCF	POUNDS PER CUBIC FOOT
CONN	CONNECTION	PL	PLATE
CONT	CONTINUOUS	PLY	PLYWOOD
CJP	COMPLETE JOINT PENETRATION	PJP	PARTIAL JOINT PENETRATION POUNDS PER SQUARE FOOT
DIA 6	DIAMETER	PSF PSI	POUNDS PER SQUARE FOOT POUNDS PER SQUARE INCH
DIA, Ø	DIAMETER	PSI	POUNDS PER SQUARE INCH
DIAG DL	DIAGONAL DEAD LOAD	RAD	RADIUS
DN	DOWN	RD	ROOF DRAIN
DO	DITTO	REINF	REINFORCING
DWG(S)	DRAWING(S)	REQ'D	REQUIRED
D110(0)	Dio titilito(o)		
(E)	EXISTING	SCHED	SCHEDULE
ÈÁ	EACH	SIM	SIMILAR
EF	EACH FACE	SOG	SLAB ON GRADE
EJ	EXPANSION JOINT	SS	STAINLESS STEEL
EL	ELEVATION	STD	STANDARD
EMBED	EMBEDMENT	STIFF	STIFFENER
EQ ES	EQUAL EACH SIDE	STL STRUCT	STEEL STRUCTURAL
EW	EACH WAY	SIRUCI	STRUCTURAL
EVV	EACH WAT	T&B	TOP AND BOTTOM
FDN	FOUNDATION	TOC	TOP OF CONCRETE
FF	FINISH FLOOR	TOS	TOP OF STEEL
FG	FINISH GRADE	TOW	TOP OF WALL
FIN	FINISH	TYP	TYPICAL
FLR	FLOOR		
FS	FAR SIDE	UON	UNLESS OTHERWISE NOTED
FT OR '	FOOT, FEET		1772024000
FTG	FOOTING	VERT	VERTICAL
	041105	VIF	VERIFY IN FIELD
GA	GAUGE GALVANIZED	W/	WITH
GALV GL	GRID LINE	W/O	WITHOUT
GR	GRADE	WP	WORK POINT
		WWR	WELDED WIRE REINFORCING
HDG	HOT-DIP GALVANIZED		
HGR	HANGER		
HORIZ	HORIZONTAL		
HSB	HIGH STRENGTH BOLT		
HSS	HOLLOW STRUCTURAL SECTION		
IBC	INTERNATIONAL BUILDING CODE		
ICC IN OR "	INTERNATIONAL CODE COUNCIL INCH, INCHES		
IN OK	וויטוו, וויטחבס		



PROJECT TEAM:

City of Cambridge

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham MA 02451

House Doctor

Arup 60 State St, Boston, MA 02109

KEY PLAN:



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave, Cambridge, MA 02139

PROJECT #: 211204 ISSUE DATE: 10/20/2022

PROJECT STATUS: Coordination Set
DRAWN BY: EJC CHECKED BY: RES

SHEET NAME: GENERAL NOTES

DRAWING HISTORY:

NO. DATE DESCRIPTION

SHEET#: **S001** 

- 1 POE	STATEMENT OF SPECIAL INSPECTIONS
LOCATION	795 Massachusetts Avenue, Cambridge MA
OWNER	City of Cambridge
DESIGN PROFESSIONAL IN CHARGE	Erik W. Farrington

This Statement of Special Inspections is submitted as a condition for permit issuance in accordance with the Special Inspection and Structural Testing requirements of the Massachusetts State Building Code, 9th Edition (MSBC). It includes a schedule of Special Inspection services applicable to this project as well as the name of the Special Inspection coordinator and the identity of other approved agencies to be retained for conducting these inspections enterpresses the following disciplines: STRUCTURAL. The Special Inspection Coordinator shall keep records of all inspections and shall furnish inspection reports to the Building Official and the Registered Design Professional in Responsible Charge (RDP). The Special Inspection Coordinator will compile and distilly all inspection reports directly to the RDP, the contractor, the owner, the building official, and any other parties designated by the owner. Discovered discrepancies shall be brought to the immediate attention of the contractor for correction. If such of his or her responsibilities for quality control (QC).

nterim reports shall be submitted to the Building Official and the RDP. Interim reports shall be submitted monthly.

A Final Report of Special Inspections documenting completion of all required Special Inspections, testing, and correction of any discrepancies noted in the inspections shall be submitted by the Special Inspection Coordinator prior to issuance of a Certificate of Use and Occupancy. The intention of the following tables is to identify the quality assurance (QA) inspection tasks as required by the 2015 International Building Code (IBC). In accordance with IBC Section 1704.2, the owner or the owner's authorized agent shall employ one or more approved testing agencies to provide special inspections. The Special Inspection Coordinator and approved agencies shall not be retained by the contractor or subcontractor whose work is to be inspected or tested. Any conflicts of interest shall be disclosed to the Authority Having Jurisdiction (AHJ) prior to commencing the work.

Job site safety and means and methods of construction are solely the responsibility of the contractor.

# SCHEDULE OF INSPECTION AND TESTING AGENCIES

SPECIAL INSPECTION AGENCIES	FIRM	ADDRESS	TELEPHONE #
Special Inspection Coordinator	TBD	TBD	TBD
Inspector	TBD	TBD	TBD

Note: The inspectors and testing agencies shall be engaged by the Owner or the Owner's Agent in accordance with Section 1704.1 the 2015 International Building Code (IBC 2015), as referenced in MSBC and not by the Contractor or Subcontractor whose work is to be inspected or tested. Any conflict of interest must be disclosed to the Building Official prior to commencing work.

# STATEMENT OF CONTRACTOR'S RESPONSIBILITY

In accordance with IBC 2015 Section 1704.4, as referenced in MSBC, each contractor responsible for the construction or fabrication of a main wind-force resisting system or a seismic-force-resisting system or a wind- or seismic-resisting component listed in the statement of special inspections above must submit a Statement of Responsibility to the Structural Engineer of Record, the building official and the owner prior to commencement of work on the system. The contractor's statement of responsibility shall contain acknowledgement of awareness of the special requirements contained in the statement of special inspections.

#### QUALIFICATIONS OF INSPECTORS AND TESTING TECHNICIANS

The qualifications of all personnel performing Special Inspection and testing activities are subject to the approval of the Building Official. The credentials of all Inspectors and testing technicians shall be provided.

Key for Minimum Qualifications of Inspection Agents:

When the Registered Design Professional in Responsible Charge deems it appropriate that the individual performing a stipulated test or inspection have a specific certification or license as indicated below, such designation shall appear below the Agency Number on the Schedule.

PE/SE	Structural Engineer – a licensed PE specializing in the design of building structures
EIT	Engineer-In-Training — a graduate engineer who has passed the Fundamentals of Engineering examination
	AMERICAN WELDING SOCIETY (AWS) CERTIFICATION
AWS-CWI	Certified Welding Inspector
ICC-SMSI	Structural Masonry Special Inspector
ICC-SWSI	Structural Steel and Welding Special Inspector

	DEFINITIONS
AHJ	Authority Having Jurisdiction is the organization, political subdivision, office, or individual charged with the responsibility of administering and enforcing provisions of the applicable building code. Also referred to as the building official.
Continuous	Where "inspection frequency" is noted as continuous, the special inspector must be present when and where the work to be inspected is being performed. Work on the items to be inspected may not proceed unless the inspector is on the site.
Document	Document means that the QC or QA inspector shall prepare reports or other appropriate written documentation indicating that the work has or has not been performed in accordance with the construction documents.
Periodic	Where "inspection frequency" is noted as periodic, the special inspector may be intermittently present where the work to be inspected has been or is being performed. Work may proceed and need not be delayed while the inspector is not on the site.
Quality Assurance (QA)	Quality Assurance procedures and inspections are established by this Statement of Special Inspections and are implemented by the Special Inspection Coordinator and approved testing agencies to provide the owner, the registered design professional, and the Authority Having Jurisdiction with independent, objective confirmation that the work is performed in accordance with the construction document.
Quality Control (QC)	Quality Control procedures and inspections are established by the contractor to ensure that their work is performed in accordance with the construction documents.

- ag	REFERENCES			
CODE/STANDARD	TITLE	Ski		1
ACI 530.1/ASCE 6/TMS 602-13	Specifications for Masonry Structures		3	
AISC 360-10	Specification for Structural Steel Buildings			_
AISC 341-10	Seismic Provisions for Structural Steel Buildings			
ASTM A6-11	Specification for General Requirements for Rolled Steel Plates, Shapes, Sheet Piling, and Bars for Structural Use			
ASTM C1314-16	Standard Test Method for Constructing and Testing Masonry Prisms			
AWS D1.1-2015	Structural Welding Code – Steel			
APPLICABLE BUILDING CODE	International Building Code 2015 with Massachusetts Amendments, Ninth Edition			
RCSC-2009	Specification for Structural Joints Using High-Strength Bolts			

POS	T-INSTALLED A	DHESIVE ANCH	IORS-ACI 318 CHAPTER 17
ITEM	AGENCY	INSPECTION FREQUENCY	SCOPE
INSTALLER QUALIFICATIONS	ACI/CRSI	PERIODIC	Review installers qualifications. Installation of adhesive anchors installed horizontally or upwardy inclined to support sustained tension loads shall be performed by personnel certified by an applicable certification program. Certification shall include written and performance test in accordance with ACI/CRSI Adhesive Anchor Installer Certification Program or equivalent.
	2	CONTINUOUS	Verify that existing reinforcing steel is not cut when drilling holes for anchors.
		PERIODIC	
		CONTINUOUS FOR ANCHORS INSTALLED HORIZONTALLY OR UPWARDLY INCLINED TO SUPPORT (BY CERTIFIED INSPECTOR)	Verify drilled holes are the proper d'ameter and depth in accordance with manufacturer's printed installation instructions (MPII)
The state of the s		PERIODIC	
		CONTINUOUS FOR ANCHORS INSTALLED HORIZONTALLY OR UPWARDLY INCLINED TO SUPPORT (BY CERTIFIED INSPECTOR)	Verify diffled holes are cleaned in accordance with MPII and that the holes are protected from contamination until adhesive is installed. A drilled anchor hole shall be re-cleaned assuming the hole was just drilled, if in the opinion of the RDP, Special Inspector, or Owner's Representative the hole has become contaminated after initial cleaning.
		PERIODIC	
ANCHOR INSTALLATION	ACI-CCSI/ICC-RCSI	CONTINUOUS FOR ANCHORS INSTALLED HORIZONTALLY OR UPWARDLY INCLINED TO SUPPORT (BY CERTIFIED INSPECTOR)	Verify that adhesive material is in accordance with the Contract Documents, Verify that the material is stored, mixed, and injected in accordance with the manufacturer's instructions.
- a .		PERIODIC	9
		CONTINUOUS FOR ANCHORS INSTALLED HORIZONTALLY OR UPWARDLY INCLINED TO SUPPORT (BY CERTIFIED INSPECTOR)	Verify anchors to be installed are clean, oil-free, and free of loose rust, paint, or other coatings.
		PERIODIC	Verify that installed adhesive anchors are securely fixed in place to prevent displacement while the adhesive cures. Unless otherwise shown on the contract
		CONTINUOUS FOR ANCHORS INSTALLED HORIZONTALLY OR UPWARDLY INCLINED TO SUPPORT (BY CERTIFIED INSPECTOR)	drawings, anchors should be installed perpendicular to the concrete surface. Anchors displaced before full adhesive our eshall be considered dramged and replaced at the Contractor's expense. Installed reinforcing bars/threaded bars shall not be bent after being adhesively embedded in hardened, sound concrete, unless permitted by the RDP.
		CONTINUOUS	Verify that the anchor materials, lengths, dameters, embedments, and finishes are in accordance with the Contract Documents.
**	ACI-CCSI/ICC-RCSI	CONTINUOUS	Adhesive anchors shall be proof-tested as required in the contract documents. A minimum of 5% of each type and size of an adhesive anchor assembly shall be proof tested in tension by an independent testing laboratory. Tension testing shall be performed in accordance with ASTM E488. The independent testing laboratory shall submit an anchorage testing plan to the RDP to ensure the testing requirements are fulfilled.
ADHESIVE ANCHOR PROOF TESTING	ACI-CCSI/ICC-RCSI	CONTINUOUS	The adhesive anchors shall be tension proof loaded to loads indicated in the contract documents for a specific anchor type. Proof loading shall be performed after a minimum curing period specified by the manufacturer. Anchors shall have no visible indications of displacement or damage during or after proof load application. Concrete cracking in the vicinity of the anchor after loading shall be considered a failure.
			If any of the tested adhesive anchors fall to achieve the specified proof load within the limits defined on the contract documents, 25% of the anchors of the same dameter and type as the failed anchor shall be proof tested, unless otherwise direct by the RDP.

	ı	MASONRY-IBC	2015 SECTION 1705.4
ITEM	AGENCY	INSPECTION FREQUENCY	SCOPE
MATERIAL CERTIFICATION	ICC-SMSI	PERIODIC	Review certificates of all masonry material, reinforcement, and accessories for compliance with ACI-530.1 Sections 2.1, 2.2, 2.3, 2.4, and 2.5 and with the Contract Documents.
MIXING OF MORTAR AND GROUT	ICC-SMSI	PERIODIC	Inspect all mortar and grout mixes, mixing operations, and re-tempering for compliance with ACI 530.1 Section 2.6 and with the Contract Documents.
INSTALLATION OF MASONRY	ICC-SMSI	PERIODIC	Inspect size, layout, bonding, and placement of masonry units. Inspect installation of masonry units for compliance with ACI 530.1 Section 3.2 and 3.3, and with the Contract Documents.
MORTAR JOINTS	ICC-SMSI	PERIODIC	Inspect construction of mortar joints, including tooling and filling of head joints.
REINFORCEMENT INSTALLATION	ICC-SMSI	PERIODIC	Inspect installation of reinforcement prior to grout placement for compliance with ACI 530 Chapter 8, ACI 530.1 Section 3.4 and 3.6 and with the Contract Documents. Verify grade, size, type, and position of reinforcement.
		CONTINUOUS	Verify that grout space is clean and cleanouts are provided (for high-lift grouting) prior to grouting.
GROUTING OPERATIONS	ICC-SMSI	CONTINUOUS	Inspect grout placement operations for compliance with ACI 530.1 Section 3.5 and with the Contract Documents.
WEATHER PROTECTION	ICC-SMSI	PERIODIC	Inspect that hot- and cold-weather-protection procedures compty with ACI 530.1 Section 1.8 and with the Contract Documents. Verify that wall cavities are protected against precipitation.
100		PERIODIC	Determine compressive strength of masonry per ACI 530.1 Section 1.4 and 1.6.
5,41,147,01,05		PERIODIC	Observe preparation of mortar and grout cubes. Observe preparation of masonry prisms.
EVALUATION OF MASONRY	ICC-SMSI	PERIODIC	Test compressive strength of mortar and grout cube samples (ASTM C780).
STRENGTH		PERIODIC	Test compressive strength of masonry prisms (ASTM C1314). Test three prisms prior to the start of construction and one prism for every 5,000 sq ft thereafter for each type of unit used.
ANCHORS AND TIES	ICC-SMSI	CONTINUOUS	Inspect all anchorage to masonry (including masonry veneers) for compliance with ACI 530 Sections 4.2 and 5.14 and with Contract Documents.
		CONTINUOUS	Verify that existing reinforcing steel is not cut when drilling holes for anchors.
EXPANSION ANCHORS	ICC-RCSI	CONTINUOUS	Inspect installation. Verify manufacturer, type, diarneter, material, markings, seating of washer, embedment and torque of anchors are in accordance with the Contract Documents.

#### Finegold Alexander Architects

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Erwelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham MA 02451

Arup 60 State St, Boston, MA 02109

KEY PLAN:



PROJECT INFORMATION:


Cambridge - City Hall Facade Restoration 795 Massachusetts Ave, Cambridge, MA 02139

PROJECT #: 211204 ISSUE DATE: 10/20/2022 PROJECT STATUS: Coordination Set CHECKED BY: RES

SPECIAL TESTING AND


DIVIII	ING HISTORY	: 8
NO.	DATE	DESCRIPTION

**S002** 



Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham MA 02451

House Doctor Arup 60 State St, Boston, MA 02109






Cambridge - City Hall Facade Restoration

PROJECT #: 211204
ISSUE DATE: 10/20/2022
PROJECT STATUS: Coordination Set
DRAWN BY: EJC
CHECKED BY: RES

SOUTH ELEVATION

DRAWING HISTORY: NO. DATE DESCRIPTION

**S100** 




SECTION AT FLAGPOLE

2 FLAGPOLE BASE PLATE DETAIL



(E) STRUT ATTACHMENT



 FLAGPOLE MANUFACTURER TO REPLACE (E) STRUT WALL BRACKET AND ANCHORAGE TO MATCH (E).

(N) STRUT ATTACHMENT

REPAIR STONE MASONRY AT (E) STRUT CONNECTION LOCATION, SEE EN-SERIES DWGS

1/2/9 SS THROUGH BOLT, PROVIDE ARCHITECTURAL COPPER CAP OVER BOLT HEAD AND PLATE, SIM TO EXISTING CONDITIONS, NOTE 1.

(N) SS FLAGPOLE STRUT CONNECTION TO (E) STONE MASONRY WALL BY FLAGPOLE MANUFACTURER, GC TO DOCUMENT DIMENSION AND PROFILE OF CONNECTION AND HARDWARE FOR EOR AND FLAGPOLE MANUFACTURER REFERENCE

(N) COPPER FLAGPOLE STRUT, BY FLAGPOLE STRUT, BY FLAGPOLE MANUFACTURER REFERENCE

NOTES:

 GC TO SUBMIT PRODUCT INFORMATION FOR ARCHITECTURAL FINISHES AT STRUT CONNECTION FOR ARCH/OWNER REVIEW.

SECTION AT STRUT ATTACHMENT

Finegold Alexander Architects

PROJECT TEAM:

OWNER: City of Cambridge 795 Massachusetts Ave, Cambridge, MA 02139

Structural & Envelope Simpson Gumpertz & Heger 480 Totten Pond Rd, Waltham MA 02451

House Doctor Arup 60 State St, Boston, MA 02109

KEY PLAN:

SEA



PROJECT INFORMATION:

Cambridge - City Hall Facade Restoration 795 Massachusetts Ave. Cambridge, MA 0

PROJECT #: 211204
ISSUE DATE: 10/20/2022
PROJECT STATUS: Coordination Set

DRAWN BY: EJC
CHECKED BY: RES
SHEET NAME:

SECTIONS AND DETAILS

DRAWING HSTORY:
NO. DATE DESCRIPTION

SHEET#:

**S110** 

