

LEGEND

Drainage Issues

Sewer Issues

Pedestrian Issues

Driving Issues

Cycling Issues

Miscellaneous Issues

Fire Station

Playground

School



One Way Street Direction

71

Address

@

Catch Basin



GLOBAL ISSUES

- DRAINAGE ISSUES

MANY PROPERTIES WITH PONDING/FLOODING ISSUES.

UNDERGROUND STREAMS ARE PRESENT ALONG STANDISH STREET AND BETWEEN STANDISH STREET AND CHILTON STREET CAUSING MANY FLOODING ISSUES IN HOUSE, YARD, AND STREET.

WATER RUNOFF COMES DOWNHILL FROM HURON AVE AND INTO BACKYARDS ON STANDISH STREET.
- SEWER ISSUES

NONE REPORTED.
- PEDESTRIAN ISSUES

SIDEWALKS ARE GENERALLY UNEVEN AND NOT EASILY ACCESSIBLE.
- DRIVING ISSUES

MANY DRIVE WRONG WAY ON VASSAL LANE AND STANDISH STREET.

MANY CARS SPEED DOWN STANDISH STREET.

THERE ARE SEVERAL SINKHOLES ON STANDISH STREET.

THERE ARE MANY POTHOLES ON VASSAL LANE EAST OF STANDISH STREET.

BUSES GO DOWN STANDISH STREET TO GET TO THE SCHOOL. SOME RESIDENTS THOUGHT THE BUSES ARE RESTRICTED TO LAKEVIEW AVENUE.

PARKING IS WELL UTILIZED ON STANDISH STREET. SOME RESIDENTS ARE CONCERNED FOR POTENTIAL LOST OF PARKING.
- CYCLING ISSUES

CYCLISTS RIDE IN THE MIDDLE OF THE ROADWAY BECAUSE ROADWAYS ARE TOO NARROW.

CYCLISTS GO THE WRONG WAY ON VASSAL LANE.

GLOBAL SUGGESTIONS


- MISCELLANEOUS SUGGESTIONS

CONSIDER CHANGING DIRECTION OF SCHOOL DRIVEWAY.

CONSIDER PROVIDING ORGANIZED DROP-OFF, PICK-UP FOR THE SCHOOL ON VASSAL LANE.

SIGNAGE IN AREA IS LESS PROMINENT; RECOMMEND MORE SIGNAGE.

ADD MORE TREES TO STANDISH STREET.



HURON A PROJECT AREA STANDISH ST, VASSAL LN, WATERMAN RD

COMMENTS INCLUDED IN THIS FIGURE ARE FROM SURVERY RESPONSES AND COMMUNITY MEETING INPUT THROUGH 03.01.11

