Cambridge Transportation Study: Inman Square

Inman Square

Cambridge Hospital – 2nd Floor

June 22, 2016



Project Background

- Study started in Summer 2015
 - Vanasse Hangen Brustlin, Inc. (VHB)
- Complaints of high delay for all modes of transportation
 - Long wait for pedestrians
 - High volumes of bicyclists
- Existing operational deficiencies
 - Crosswalk issues
 - ► Large intersection for bicyclists and vehicles



Study Goals

- Improve safety for all users
- Improve/simplify operations for all modes
- Continue to support the local residential and business communities
- Develop improvements that can be implemented in the short- to mediumterm



Average Daily Traffic Volumes

- Vehicles per Day
- Traffic Volumes from Counts conducted May, 2015




Crash Data

- Collected data from 2008-2012
- 69 total crashes in five years
- Intersection exceeds MassDOT Statewide Average Crash Rate
- ▶ 15 bicycle involved crashes, 5 pedestrian involved crashes
- Most frequent crash type angle crash
- Crash severity
 - ▶ 0 Fatal crashes
 - ▶ 21 Injury crashes



Existing Pedestrian Routing

- Existing Long Crosswalks
- Some crosswalks do not provide signal control
- Crosswalks outside pedestrian desire lines
- High delay at crosswalks reduces compliance with signals
- Hampshire Street south crosswalk is far from the main intersection zone




Existing Fire Station Access

- Any proposed changes need to maintain full access to Fire House
- Signal provides pre-emption phase




Existing Signal Control Concerns

 No signal control for Hampshire Street southbound to Antrim Street




Existing Signal Control Concerns

- No signal control for Hampshire Street southbound to Antrim Street
- No signal control for crosswalk across
 Antrim Street or
 Hampshire Street turn lane




Existing Geometry Issues

- 270' between STOP bars on Hampshire Street & Cambridge Street
- Long distance for bikes to travel




Existing Geometry Issues

- 270' between STOP bars on Hampshire Street & Cambridge Street
- Long distance for bikes to travel
- Clearance times for vehicles turning



Existing Geometry Issues

- 270' between STOP bars on Hampshire Street & Cambridge Street
- Long distance for bikes to travel
- Clearance times for vehicles turning
- Lane control on Cambridge Street is unclear



Desired Outcomes

Pedestrian

- Provide improved sidewalks
- Expand open space
- Provide more crossing opportunities
- Reduce the length of crosswalks

Bicycle

- Reduce exposure through more compact intersection design
- Minimize conflicts with turning vehicles
- Provide separation if feasible

Vehicle

- Reduce unnecessary delay
- Provide clear guidance and lane controls
- Increase efficiency through more compact intersection design



 Compact intersections reduce exposure time for bikes



- Compact intersections reduce exposure time for bikes
- Expanded open space




- Compact intersections reduce exposure time for bikes
- Expanded open space
- Construct two new traffic signals



- Compact intersections reduce exposure time for bikes
- Expanded open space
- Construct two new traffic signals
- More crossing opportunities, crosswalks reduced in length



- Compact intersections reduce exposure time for bikes
- Expanded open space
- Construct two new traffic signals
- More crossing opportunities, crosswalks reduced in length
- Signal control will provide continuous movement on Hampshire Street
- Left turn movements for bikes need additional consideration






 Compact intersections reduce exposure time for bikes




- Compact intersections reduce exposure time for bikes
- Expanded open space




- Compact intersections reduce exposure time for bikes
- Expanded open space
- Construct two new traffic signals



- Compact intersections reduce exposure time for bikes
- Expanded open space
- Construct two new traffic signals
- More crossing opportunities, crosswalks reduced in length



- Compact intersections reduce exposure time
- Expanded open space
- Construct two new traffic signals
- More crossing opportunities, crosswalks reduced in length
- Signal control will provide continuous movement on Cambridge Street
- Through bikes on Hampshire Street do not need to turn
- May require operational changes on Springfield Street



Next Steps

- Discussion with Community
- Ongoing Coordination
 - ▶ City of Somerville
 - ▶ Fire Department
- Identify funding opportunities
- Begin design efforts Fall 2016 pending community input



Questions?

